### **Optimizer** offline

At the first point please do the following via fusiosnsolar web.


- Check the inverter and MBUS firmwares, upgrade if needed
- Search optimizers during a good sunny weather.

## If it doesn't solve the issue please proceed below at onsite


- 1) Login locally via fusionsolar app
- 2) Check the current version of MBUS, if it is other than V100R001C00SPC330 then do upgrade (*Take screenshot/picture*).

#### https://photomate.zendesk.com/hc/en-gb/articles/4707331277213-MBUS-DC-for-Inverters


- 3) Check that the SN and location information of the optimizers are correct
- 4) Search for the optimizers again during the irradiance is good (*Take screenshot/picture*). Maintenance-> Subdevice Management -> Search optimizers



5) Check the current version of optimizer, if it is other than V100R002C10SPC019 then do upgrade, when the irradiance is good (*Take screenshot/picture*).



6) Measure the PV string resistance. Example: for 6 optimizers the resistance should be 6kOhm +/- 10%. (*Take picture*).





If it is different, then measure the resistance of individual disconnected optimizers (it should be 1 kOhm per optimizer).

1. Connect the optimizer input power cables.

2. Connect the positive probe of the multimeter to the positive output terminal of the optimizer and the negative probe to the negative output terminal. Check the output voltage and resistance of a single optimizer.








- The voltage V1 is 0 V.
- The resistance R1 is 1 k $\Omega$  ( $\pm$ 10%).

If the probes are reversely connected, the measured resistance is less than the resistance measured when the probes are correctly connected, which might be less than  $0.9~\mathrm{k}\Omega$ .


Resistance	Cause	Suggestions
$0.9 \text{ k}\Omega \leq \text{R1} \leq 1.1 \text{ k}\Omega$	The optimizer is normal.	N/A
R1 < 0.9 kΩ	If the probes of the multimeter are correctly connected, the optimizer is faulty.	Replace the optimizer.
1.1 kΩ < R1	<ul> <li>The sunlight is weak.</li> <li>The optimizer input is not connected.</li> <li>The optimizer output is connected to the PV module output.</li> <li>The optimizer is faulty.</li> </ul>	<ol> <li>Measure the resistance when the sunlight is sufficient.</li> <li>Connect the optimizer input power cables.</li> <li>Correct the optimizer cable connection.         Connect the optimizer input power cables to the output cables of the PV module.     </li> <li>If the resistance is still abnormal, replace the optimizer.</li> </ol>

# **Common Exception Scenarios**




3. Check that the optimizer input is properly connected, and connect the output power cables to the optimizer. Measure the PV string resistance when the sunlight is sufficient.

### **Full Configuration of Optimizers**



7) Check whether the input and output terminals of the optimizers are reversely connected and also optimizer extension cable made correctly. (*Take picture*)



- 8) Measure the RISO on fully optimized strings (Take picture).
- Verify safe string voltage and current: max. 50V and 500mA.
- Connect the positive and negative connectors of the first or last optimizer in the string to the branch cable.
- Connect the positive probe of the insulation tester to the branch cable.
- Connect the negative probe of the insulation tester to a ground point.
- Select 500V testing on the insulation tester.
- Test the insulation.

If the resistance is less than  $600k\Omega$  in a single phase inverter or less than  $1M\Omega$  in a three phase inverter, continue checking this string's components to isolate the source of leakage. Always make sure to connect both negative and positive output connectors to the tester using a branch cable.

